

# Bluesbreaker


## Components

<b>C1</b>	10nF	<b>R1</b>	1M	<b>GAIN</b>	100K Linear
<b>C2</b>	47pF	<b>R2</b>	4K7	<b>VOLUME</b>	100K Log
<b>C3</b>	10nF	<b>R3</b>	3K3	<b>TONE</b>	25K Linear
<b>C4</b>	10nF	<b>R4</b>	1M	<b>TREBLE</b>	solder jumper as shown below
<b>C6</b>	100nF	<b>R5</b>	Jumper		
<b>C7</b>	10nF	<b>R6</b>	4K7	<b>D1-4</b>	1N4148
<b>C8</b>	10nF	<b>R8</b>	6K8	<b>D5-6</b>	none
<b>C9</b>	100nF	<b>R9</b>	220K	<b>D7</b>	1N4001
<b>C10</b>	100uF Electrolytic	<b>R10</b>	6K8		
<b>C11</b>	100uF Electrolytic	<b>R11</b>	1K	<b>IC1</b>	TL072
<b>C12</b>	none	<b>R12</b>	1M		
		<b>R13</b>	47K	<b>DIODES SWITCH</b>	solder jumper as shown below
		<b>R14</b>	47K		

Note: there is no C5 or R7

## Jumpers

Where a component is listed as jumper, solder a piece of wire between the pads to make a connection. Where the treble trimmer is not used, you should put a jumper between pins 2 and 3 like the diagram below. If you're building the Bluesbreaker, put a jumper between the bottom two pads of the DIP switch



Treble



Diodes

# Bluesbreaker

## Board Connections

The PCB connections are labelled as the following:

I - Input, O - Output, V - 9V DC in, G - Ground

Potentiometers are connected from pin 1 to the square pad on the PCB. This board was designed so you can use right-angle board mount potentiometers on it if desired, otherwise you will need to solder wires from the pads to the correct pin/lug. Jack sleeves and DC centre pin should be connected to ground. V should be connected to the positive pin of the DC connector.

